


Page 1 of 18




Page 2 of 18




Page 3 of 18



Page 4 of 18








FIG. 6




FIG. 7A






FIG. 7B





Matter No.: 10406-006003 Pa. Applicant(s): Norman J. MacDonald III et al. FIRE PROTECTION SPRINKLER HEAD SUPPORT 110 126 FIG. 9 128 122 136 134 12 132-20 -130 14 FIG. 10


Page 8 of 18


Page 9 of 18















Matter No.: 10406-006003 Pag-Applicant(s): Norman J. MacDonald III et al. FIRE PROTECTION SPRINKLER HEAD SUPPORT 192

Page 16 of 18



Page 18 of 18

